

NOTES

FOR PRESTRESSED GIRDER REPAIR DETAILS, SEE "PRESTRESSED GIRDER REPAIR DETAILS AND SUMMARY" SHEET.

THE LOCATIONS AND DIMENSIONS OF THE AREAS FOR REPAIR ARE BASED ON THE BEST INFORMATION AVAILABLE. THE CONTRACTOR, IN CONJUNCTION WITH THE ENGINEER, SHALL VERIFY THE LOCATION AND EXTENT OF REPAIR AREAS PRIOR TO GIRDER REPAIR.

① GIRDER NUMBER

GIRDER REPAIR LOCATIONS			
GIRDER	LOCATION	REPAIR SIZE ( L x W )	LABEL
1	BT. FL.	10" x 10"	A
1	WEB & BT. FL.	1'-5" x 1'-5"	B
2	BT. FL.	1'-0" x 1'-0"	C
3	WEB & BT. FL.	1'-5" x 1'-6"	D
3	R.S. OF BT. FL.	1'-1" x 11"	E
5	L.S. OF BT. FL.	1'-4" x 1'-2"	F
5	R.S. OF BT. FL.	1'-5" x 1'-2"	G
5	TOP FL. END	1'-0" x 1'-0"	H
5	BT. FL.	7" x 10"	I

PRESTRESSED GIRDER REPAIR LOCATIONS


(OTHER LOCATIONS MAY EXIST, SEE NOTES)

PROJECT NO. 15BPR.18

DAVIE COUNTY

BRIDGE NO. 63

SHEET 7 OF 10



STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION RALEIGH						SHEET NO.	
PRESTRESSED GIRDER REPAIR LOCATIONS						S-15	
SPAN G						TOTAL SHEETS	
REVISIONS						38	
NO.	BY:	DATE:	NO.	BY:	DATE:		
1			3				
2			4				

DRAWN BY : H.A. LOCKLEAR DATE : 6-18

CHECKED BY : M.G. SHAIKH DATE : 6-18

DOCUMENT NOT CONSIDERED  
FINAL UNLESS ALL  
SIGNATURES COMPLETED